

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] []

PLEASE PRINT ALL REQUIRED INFORMATION

LICENSE NAME: N Y I P S 2 | LICENSE NUMBER: 0 0 - 0 0 | LICENSE TYPE: 4 1 | 1 1 | 1 | EVENT TYPE: 0 | 1

CONT: CATEGORY: P 0 | REPORT TYPE: L | REPORT SOURCE: L | DOCKET NUMBER: 0 5 0 - 0 2 4 7 | EVENT DATE: 1 2 1 8 7 5 | REPORT DATE: 0 1 1 6 7 6

EVENT DESCRIPTION

During normal operation, excessive leakage was observed from the fluid head of Charging Pump No. 23. Charging Pump No.21 had previously exhibited a very slight similar leak. Charging Pump No.21 remained operable despite the pinhole leak. Charging Pump No.22 was also operable during this time. New fluid heads were installed on Charging (Cont'd)

SYSTEM CODE: P C | CAUSE CODE: E | COMPONENT CODE: P U M P X X | PRIME COMPONENT SUPPLIER: N | COMPONENT MANUFACTURER: U O S S | VIOLATION: N

CAUSE DESCRIPTION

The variable speed, positive displacement, 98 gpm type QX-300 Quintuplex pump became inoperative when a crack had developed in the fluid head. The head was subsequently replaced and the pump returned to service.

FACILITY STATUS: E | % POWER: 1 0 0 | OTHER STATUS: NA | METHOD OF DISCOVERY: B | DISCOVERY DESCRIPTION: Routine Daily Inspection

FORM OF ACTIVITY RELEASED: Z | CONTENT OF RELEASE: Z | AMOUNT OF ACTIVITY: NA | LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER: 0 0 0 | TYPE: Z | DESCRIPTION: NA

PERSONNEL INJURIES

NUMBER: 0 0 0 | DESCRIPTION: NA

PROBABLE CONSEQUENCES

NA

LOSS OR DAMAGE TO FACILITY

TYPE: Z | DESCRIPTION: NA

PUBLICITY

NA

ADDITIONAL FACTORS

(Event Description-Cont'd): Pump No. 23 on December 21, 1975 and on Charging Pump No. 21 on December 24, 1975. (A.O.-75-2-30(B)).

NAME: Michael Shatkouski | PHONE: (914)-739-8823

3111070412 760116 DR ADDCK 05000247 PDR