



Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003

February 4, 1976

Re: Indian Point Unit No. 2  
AEC Docket No. 50-247

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement, Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following confirms the oral notification to Mr. John Streeter of your office on February 3, 1976 of Reportable Occurrence No. 76-2-5 (A). The occurrence is the type defined by Regulatory Guide 1.16, Revision 4, Section C.2.a(9).

An inspection of all hydraulic snubbers not accessible during normal reactor operation was initiated in conjunction with a unit shutdown which began on January 29, 1976. A review of the results of these inspections indicates that one of the Bergen-Paterson hydraulic snubbers did not meet the requirements for operability because of insufficient fluid reserve. The snubber (52 SR-713), which was located on the discharge from No. 22 accumulator, was replaced.

Very truly yours,

*Walter Stein*  
Walter Stein, Manager  
Nuclear Power Generation  
Indian Point Station  
Buchanan, New York 10611

Copy to: Director of Nuclear Reactor Regulation  
Attn: Mr. William F. McDonald, Director (2 copies)  
Office of Management Information and  
Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

8111090135 760204  
PDR ADOCK 05000247  
S PDR