



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

July 31, 1975

Re: Indian Point Unit No. 2
AEC Docket No. 50-247

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following report of Abnormal Occurrence No. 75-2-14(A) confirms the telephone report to Mr. Anthony Fasano of your office on July 31, 1975.

The occurrence is the type defined by Regulatory Guide 1.16, Revision 3, Section C.2.a(9).

During the conduct of Periodic Surveillance Test PT-SA1 on July 30, 1975, it was found that the pressure drop across the demister and HEPA filters for Fan Cooler Units No. 22 and No. 25 was slightly higher than that allowed by Technical Specifications. At the time of the occurrence, Unit No. 2 was in the cold shutdown condition for a scheduled outage which began on July 28, 1975.

Our investigation into the cause of the occurrence has not yet been completed and is continuing. However, a preliminary review of the occurrence indicates that the safety implications are not significant.

Very truly yours,

Walter Stein


Walter Stein, Manager
Nuclear Power Generation
Indian Point Station
Buchanan, New York 10511

Copy to: Mr. Donald F. Knuth

8111090257 750731
PDR ADOCK 05000247
S PDR



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003



July 31, 1975

Re: Indian Point Unit No. 2
AEC Docket No. 50-247

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following report of Abnormal Occurrence No. 75-2-14(A) confirms the telephone report to Mr. Anthony Fasano of your office on July 31, 1975.

The occurrence is the type defined by Regulatory Guide 1.16, Revision 3, Section C.2.a(9).

During the conduct of Periodic Surveillance Test PT-SA1 on July 30, 1975, it was found that the pressure drop across the demister and HEPA filters for Fan Cooler Units No. 22 and No. 25 was slightly higher than that allowed by Technical Specifications. At the time of the occurrence, Unit No. 2 was in the cold shutdown condition for a scheduled outage which began on July 28, 1975.

Our investigation into the cause of the occurrence has not yet been completed and is continuing. However, a preliminary review of the occurrence indicates that the safety implications are not significant.

Very truly yours,

Walter Stein

Walter Stein, Manager
Nuclear Power Generation
Indian Point Station
Buchanan, New York 10511

Copy to: Mr. Donald F. Knuth ✓