



Attachment

Docket No. 50-247

Consolidated Edison Co. of N.Y., Inc.

LER-81-001/01 T-0

Indian Point Unit No. 2

In the course of a review of the service water piping associated with the containment fan coolers at Indian Point No. 2, we believe that we have discovered a potential generic condition not specifically considered in the safety analysis report or the technical specifications that may require some corrective action to prevent the development of a situation which might occur under certain LOCA conditions if there were also simultaneous leakage from the motor coolers or associated piping. The return lines from the motor coolers inside containment as provided in the original plant design are not equipped with monitors to detect the presence of radioactivity in these lines under these postulated conditions.

Our review of this condition is continuing and appropriate corrective actions will be taken before Unit No. 2 is returned to service.