
PROD. & LITIL, EAC. 50-217

DERLIN, ROISMAN AND KESSLUN 1712 N STREET, NORTHWEST WASHINGTON, D. C. 20036

EDWARD JERLE, ANTHONY I ROISMAN GLADYS KECSLER DAVIS II. CASHOAN AREA CODE 202 PHONE 633:5070

January 19, 1972

Samuel W. Jensch, Esq. Chairman Atomic Safety & Licensing Board U.S. Atomic Energy Commission Washington, D.C. 20545



Re: Consolidated Edison Company of New York (Indian Point Unit No. 2) Docket No. 50-247

Dear Mr. Chairman:

In its letter of January 17, 1972, the Applicant provides a substantially more abbreviated statement of its progress on fire damage repair than we believe is appropriate. We believe that as to each repair undertaken, the Applicant should refer to its previous fire damage statement which was introduced into the record on December 14th and to its answers to interrogatories propounded by CCPE which were introduced into the record on January 12th. These references should indicate whether the repair as originally described was undertaken, if not, why not and a detailed explanation of the change. In addition, where tests or inspections were vet to be run, the results of each of those tests related to the specific equipment or structures tested should be disclosed and the further steps to be taken with respect to equipment which has not bassed the test or inspection should be indicated. We also feel that the results of cleaning and testing which do not show further damage, but do indicate effects which differ from those predicted (i.e. temperature, nature of soot, etc.) should be disclosed and fully explained.

8111040245 720119 PDR ADDCK 05000247 G PDR

hearing

January 19, 1972 page 2

For example, in its January 17th letter, Applicant indicates that motor testing and testing and recalibration of instruments is in progress but does not indicate which, if any, motors or instruments were found to need further repair. The failure of splices to meet fire tests is indicated but there is no explanation of the cause of this failure. Is the unspliced wire equally defective? The splice modification (fiberglass sheating) is not fully explained nor is its impact on the problem of heat buildup at the splice or of the spliced wire discussed.

We believe that the scope of the fire damage, the substantial repair work required and the significance of much of the equipment to plant and public safety requires the Applicant to provide data comparable in detail to the FSAR with respect to the repair of fire damage. If this is not done, the Applicant will not be able to establish that the plant has been constructed in compliance with its construction permit.

Sincerely,

Anthony Z. Roisman

Counsel for Citizens' Committee
for Protection of the Environment

AZR/cj

cc: All parties of record

Secretary, AEC	DATE OF DOCUMENT	Jan. 17, 1972	No.: 273	
Washington, D.C.	No Letter of Tran		OTHER:	· g
TO:	ORIG.: CC:	OTHER:		
ABC	ACTION NECESSARY  NO ACTION NECESSARY	CONCURRENCE COMMENT	DATE ANSWERED:	
CLASSIF.; POST OFFICE  REG. NO:	FILE CODE: 50-247			
No Letter of Transmittal Rec'd	REFERRED TO		CEIVED BY	DATE
	DeYoung	1-17-72		
	w/2 cys for AC	Tion	·	
	DISTRIBUTION:			
HEARING TRANSCRIPTS for Indian Point Station Unit No. 2 PAGES: 4350 thru 4593 dtd 1-11-72	Reg File Cy Compliance	(2)		_
			·	
(5 cys encl rec'd)				
REMARKS:		DO NO	IT REMOVE	
			273	DL
<b>U. S. ATC</b>	DMIC ENERGY COMMISSION N	MAIL CONTROL	FORM FORM (8-	AEC-326 60)