



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 645-3941

August 26, 1969

J. P. O'Reilly, Chief, Reactor Inspection & Enforcement Br.,
Division of Compliance, Headquarters

CONSOLIDATED EDISON COMPANY, INDIAN POINT NO. 2
DOCKET NO. 50-247

The attached report of visits to the subject facility on June 17, July 1
and 2, 1969, is forwarded for information.

Con Ed is continuing their in-depth review of piping and fittings to
establish the "pedigree" of material used. The regular on-site construction
inspection program identified two defective pieces of safety injection
piping (CO Report No. 247/69-6). During the present inspection, it was
determined that the two defective pieces were returned to the manufacturer
for repairs.

The inspector noted that carbon steel supports had been welded to auxiliary
coolant stainless steel piping. During subsequent discussions it was
learned that Con Ed was aware of the condition and that corrective action
had been initiated.

The report contains information on the purchase specifications for valves
used at the facility. This information had been requested by CO:HQ.

N. C. Moseley
Senior Reactor Inspector

Attachment:

CO Report No. 247/69-7
by G. L. Madsen, dated 8/19/69

cc: E. G. Case, DRS
R. S. Boyd, DRL (2)
S. Levine, DRL (6)
D. J. Skovholt, DRL (3)
L. Kornblith, Jr., CO
Regional Directors, CO
→ REG File

8111030051 690826
PDR ADOCK 05000247
Q PDR