


REG files



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION I  
970 BROAD STREET  
NEWARK, NEW JERSEY 07102

AREA CODE: 201-  
TELEPHONE: 645-

IN REPLY REFER TO:

June 3, 1969

J. P. O'Reilly, Chief, Reactor Inspection and Enforcement  
Branch, Division of Compliance, HQ

CONSOLIDATED EDISON COMPANY - INDIAN POINT NO. 2  
DOCKET NO. 50-247

The attached report of a visit to the subject facility on  
April 22 and 23, 1969, is forwarded for information. It is  
noted that this report covers a short initial review of  
general allegations about quality of piping and components  
at several nuclear plants, including Indian Point No. 2.

Subsequent to this inspection, G. W. Reinmuth, CO:HQ, visited  
the shop where the Allegheny Ludlum welded pipe was fabricated.  
He observed that this shop can weld pipe without filler metal  
in the sizes observed during the site inspection. It was noted  
by Reinmuth that the pipe welded without filler metal appears  
visually to be almost identical to a weld where filler metal  
is used. Subsequent to the site inspection, it was also  
determined that through an error, the inspectors were given  
specifications for Indian Point No. 3 rather than for Indian  
Point No. 2. It, therefore, appears that some, if not all of  
the differences the inspectors observed between components  
and specifications, may be resolved by reference to the proper  
specifications.

Clarification of these matters, together with an evaluation  
of Con Ed's followup program into the allegations, will be  
included in the next inspection report.

N. C. Moseley  
Senior Reactor Inspector

Enclosure:  
CO Report No. 247/69-5  
by J. H. Tillou  
dtd 5/27/69

8111030096 690603  
PDR ADOCK 05000247  
Q PDR

cc: E. G. Case, DRS  
R. S. Boyd, DRL (2)  
S. Levine, DRL (6)  
D. J. Skovholt, DRL (3)  
L. Kornblith, Jr., CO  
Regional Directors, CO  
REG files