



UNITED STATES  
ATOMIC ENERGY COMMISSION

DIVISION OF COMPLIANCE  
REGION I  
970 BROAD STREET  
NEWARK, NEW JERSEY 07102

~~D. MOSELEY~~ 201 645-  
~~R. TEDESCO~~  
~~C. LONG~~  
~~D. IRLAND~~  
~~G. WATTS~~  
files

October 17, 1968

J. P. O'Reilly, Chief, Reactor Inspection & Enforcement Br.,  
Division of Compliance, Headquarters

CONSOLIDATED EDISON COMPANY - INDIAN POINT NO. 2  
DOCKET NO. 50-247

The attached report of visits to the subject facility on September 27 and 30, 1968, and October 8, 1968, by the assigned inspector is forwarded for information. No deviations from the SAR were noted.

Field receipt inspection by the licensee detected surface cracks in one section of six-inch 304 stainless steel safety injection piping furnished by the Dravo Company. Con Ed and its contractors are pursuing this problem vigorously.

Storage of some large equipment in outside locations covered with tarps and plastic, seems to be less than desirable. We intend to continue investigation in this area in an attempt to detect any indication of adverse effects from these storage conditions.

Design criteria for power and control cable tray loading were reviewed. No deficiencies were noted.

*N. C. Moseley*  
N. C. Moseley,  
Senior Reactor Inspector

Attachment:

CO Report No. 247/68-5  
by G. L. Madsen, dtd 10/17/68

cc: E. G. Case, DRS  
→ R. S. Boyd, DRL (2)  
S. Levine, DRL (6)  
D. J. Skovholt, DRL (3)  
L. Kornblith, Jr., CO  
Regional Directors, CO  
REG Files

8111030214 681017  
PDR ADOCK 05000247  
Q PDR