

UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

201 645-3942

July 13, 1970

J. P. O'Reilly Chief, Reactor Inspection and Enforcement Branch,
Division of Compliance, HQ


CONSOLIDATED EDISON COMPANY - INDIAN POINT NO. 2
DOCKET NO. 50-247

The attached report of inspection visits on May 22, 25, 26, June 3,
11, 12, 15 and 16, 1970 is forwarded for information. No items of
nonconformance were identified.

The Con Ed and Wedco programs for design and installation review for
redundancy of electrical and control cables appears to be adequate.
We expect additional effort to be expended in making these reviews
for instrumentation.

During a review of containment piping penetrations, U. S. Testing de-
tected excessive rust and some questionable quality welds. These con-
ditions are being investigated by Con Ed. We will follow these items
in future inspections.

A preliminary review of health physics was made. No significant
deficiencies were identified.


N. C. Moseley
Senior Reactor Inspector

Enclosure:
CO Report No. 247/70-6
by Messrs. Madsen & Higginbotham
dated 7/7/70

cc: E. G. Case, DRS (3)
P. A. Morris, DRL
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
P. W. Howe, DRL (2)
L. Kornblith, Jr., CO
Regional Directors, CO
REG Files

8111120602 700713
PDR ADOCK 05000247
PDR