

UNITED STATES ATOMIC ENERGY COMMISSION

WASHINGTON, D.C. 20545

November 10, 1972

K. Kniel, Chief, PWR Branch #2, L

CONSOLIDATED EDISON COMPANY (INDIAN POINT 2) - RO INSPECTION REPORT NO. 50-247/72-09

The enclosed report of an inspection at the Westinghouse Nuclear Fuels Division, Cheswick, Pennsylvania on June 12 and 13, 1972, is forwarded for information. The purpose of the inspection was to review the Quality Assurance Program that had been employed by Westinghouse during the fabrication of the Indian Point 2 fuel assemblies.

The inspection findings indicate that the Indian Point 2 fuel was fabricated in accordance with the Quality Assurance requirements in effect at that time (1968/1969); however, that Quality Assurance Program does not satisfy the current requirements of 10 CFR 50, Appendix B. The inspection findings also suggest that the Quality Assurance Program currently in effect at the Westinghouse Nuclear Fuel Division, Columbia, South Carolina, is questionable with regard to fully satisfying Appendix B requirements.

Based on our inspection findings, a vendor inspection of the Westinghouse, Columbia, South Carolina facility is under consideration by Regulatory Operations.

J. G. Keppler, Chief,
Reactor Testing and Operations
Branch
Directorate of Regulatory Operations

Enclosure:
RO Inspection Report
No. 50-247/72-09

cc w/enclosure:

R. Minogue, RS (3)

R. L. Tedesco, L

Regional Directors

R. S. Boyd, L (2)

H. R. Denton, L (2)

DR Central File

R. C. DeYoung, L (2)

R. H. Vollmer, L

I. M. Hendri

M. Karman, GC

D. J. Skovholt, L (2) D. R. Muller, L J. M. Hendrie, L R. W. Houston, L

H. D. Thornburg, w/o encl.

R. H. Engelken, w/o encl. J. B. Henderson, w/o encl.

F. J. Nolan, w/o encl.

8111110591 721003 PDR ADDCK 05000247 Q PDR