

UNITED STATES  
ATOMIC ENERGY COMMISSION  
WASHINGTON, D.C. 20545


JAN 26 1972

D. R. Muller, Chief, PWR Branch #1, DRL

CONSOLIDATED EDISON COMPANY (INDIAN POINT), DOCKET NO. 50-247

The attached report of a CO inspection conducted on December 29-30, 1971, is forwarded for information. The inspection included examination of the restoration of the electrical wiring damaged by fire.

Consolidated Edison had initially proposed to commence the splicing work prior to reviewing the results of pertinent tests; however, at the insistence of the assigned CO inspector, the tests were conducted first. The test results indicated that the proposed splicing material was unacceptable.

  
J. B. Henderson, Chief  
Reactor Construction Branch  
Division of Compliance

Enclosure:  
As stated.

cc:w/encl.

EGCase, DRS (3)  
RSBoyd, DRL (2)  
RCDeYoung, DRL (2)  
DJSkovholt, DRL (2)  
HRDenton, DRL (2)  
AGiambusso, CO  
RHEngelken, CO

LKornblith, Jr, CO  
JPO'Reilly, CO:I  
JGDavis, CO:II  
BHGrier, CO:III  
JWFlora, CO:IV  
RWSmith, CO:V  
LDR-Central Files

8111120124 720126  
PDR ADOCK 05000247  
G PDR