


UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION I  
970 BROAD STREET  
NEWARK, NEW JERSEY 07102

201 645-3942




January 11, 1972

J. B. Henderson, Chief, Reactor Construction  
Branch, Division of Compliance, HQ

CONSOLIDATED EDISON COMPANY, INDIAN POINT NO. 2  
CO REPORT NO. 50-247/71-17

The subject inspection is forwarded for information.

The inspection was limited to an examination of the procedures used in the welding overlay on the safety injection system accumulator check valves. Four items of nonconformance were identified. These items were included in the documentation letter to the licensee.

  
E. M. Howard  
Senior Reactor Inspector

Enclosure:  
Subject Inspection Report

cc: J. G. Keppler, CO  
E. G. Case, DRS (3)  
R. S. Boyd, DRL (2)  
R. C. DeYoung, DRL (2)  
D. J. Skovholt, DRL (3)  
H. R. Denton, DRL (2)  
A. Giambusso, CO  
L. Kornblith, Jr., CO  
R. H. Engelken, CO  
CO Files  
DR Central Files ✓

8111120226 720111  
PDR ADOCK 05000247  
Q PDR