

William J. Cahill, Jr.  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003  
Telephone (212) 460-3819

November 26, 1976

Indian Point Station  
Docket Nos. 50-247  
50-286

Mr. Eldon J. Brunner, Chief  
Reactor Operations and Nuclear Support Branch  
U. S. Nuclear Regulatory Commission  
Region 1  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Brunner

This refers to an inspection conducted by your Mr. J Streeter on September 27 - October 1, 1976 of activities authorized by NRC License Nos. DPR-26 and DPR-64 at our Indian Point Station. Your November 4, 1976 letter stated that it appeared that one of our activities was not conducted in full compliance with NRC requirements. This item of apparent non-compliance was set forth in the Notice of Violation which was enclosed as Appendix A to your November 4, 1976 letter. Our response to this item is as follows:

Upon being advised by the Inspector that accumulator isolation valves 894A, 894B, 894C and 894D were correctly de-energized in the open position, but not locked, locks were immediately installed on the circuit breakers associated with these valves.

On investigation, it was found that the pre-criticality check off list, COL-1, had not been revised to reflect the latest requirements of Technical Specification 3.3.A.1.i as revised by Amendment No. 20 to the Facility Operating

8111240361 761209  
PDR ADOCK 05000247  
G PDR

License. This check off list was subsequently revised on October 4, 1976 to reflect the requirement that the accumulator isolation valves motor operators be de-energized by locking out the associated circuit breakers.

Very truly yours

*William F. Kelly*