

William J. Cahill, Jr.  
Vice President

REGULATORY DOCKET FILE COPY

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003  
Telephone (212) 460-3819

March 29, 1977  
Re: Indian Point Unit No. 3  
Docket No. 50-286

Director of Nuclear Reactor Regulation  
ATTN: Mr. Robert W. Reid, Chief  
Operating Reactors Branch No. 4  
Division of Operating Reactors  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555



Dear Mr. Reid:

In accordance with and in satisfaction of the conditions contained in paragraphs 2.C (4) (a), (b) and (d) of Amendment No. 2 to the Indian Point Unit No. 3 Facility Operating License (DPR-64), forwarded herewith please find forty (40) copies of a report prepared by Dames & Moore entitled, "Geotechnical Investigation of Ramapo Fault System in the Region of the Indian Point Generating Station, "Volumes I and II.

The report addresses in detail all of the areas of work contained in Attachment I to the Detailed Work Plan - Part I, "Supplemental Geological Investigations" which was submitted to Mr. Vassallo by letter dated June 1, 1976.

This report, together with the on-site geological report submitted in December 1975, substantiates the conclusion that the Ramapo Fault System is not capable within the meaning of Appendix A to 10CFR Part 100.

Very truly yours,

*William J. Cahill, Jr.*  
William J. Cahill, Jr.  
Vice President

copy to: George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, N.Y. 10019

B111120214 770329  
PDR ADDCK 05000286  
P PDR