

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

July 31, 1974

Re Indian Point Unit No. 3
AEC Docket No. 50-286

Mr. Robert T. Carlson, Chief
Facility Construction and
Engineering Support Branch
U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Penn. 19406

Dear Mr. Carlson

In reply to your letter of June 26, 1974 concerning the inspection conducted by Mr. Allentuck on June 11-13, 1974 at our Indian Point Unit No. 3 facility, we have the following response:

Item 1

The following corrective steps were taken on the same day:


- (a) The required sign was posted.
- (b) The craftsmen donned proper clothing.
- (c) The beverage can and candy wrappers were removed from the clean area.

Personnel involved with work on the upper internals have also been reinstructed regarding the requirements of the applicable instructions. To further assure the adequacy of this corrective action, these activities will be subject to review during an audit scheduled to be conducted within the next thirty days.

Item 2

The restraint in question was, in fact, to have been discarded. It was immediately disposed of in accordance with the established procedure on non-conforming material control. Identification requirements will be stressed in our next audit of non-conformance control. This audit is also scheduled to be conducted within the next thirty days.

Very truly yours


William J. Cahill, Jr.

8111140586 740814
PDR ADOCK 05000286
G PDR