

LICENSEE EVENT REPORT

TEIR-77-3-3

CONTROL BLOCK:

--	--	--	--	--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME			LICENSE NUMBER										LICENSE TYPE				EVENT TYPE							
01	N	Y	I	P	S	3	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	9	9
7	8	9	14	15	25	26	30	31	32															

REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE				REPORT DATE											
01	CONT	O	L	0	5	0	-	0	2	8	6	0	4	1	2	7	7	0	5	1	7	7	7
7	8	57	58	59	60	61	68	69	74	75	80												

EVENT DESCRIPTION

02 FOR INFORMATION ONLY. During startup operations, an attempt to put No. 33 motor driven auxiliary boiler feed pump into service was unsuccessful. Steam generator levels were maintained utilizing No. 31 and 32 auxiliary boiler feed pumps. No. 33 auxiliary boiler feed pump was removed from service for investigation and repair. [TEIR-77-3-3].

SYSTEM CODE	CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION				
07	H	H	E	P	U	M	P	X	X	N	I	0	7	5	N
7	8	9	10	11	12	17	43	44	47	48					

CAUSE DESCRIPTION

08 Upon investigation, it was found that the shaft of an Ingersoll-Rand pump, Model No. 3HMTA-9 had sheared. Repairs to the pump will be completed upon receipt and installation of required replacement parts.

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION					
11	C	0	0	0	NA	A	NA		
7	8	9	10	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE				
12	Z	Z	NA	NA			
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION				
13	0	0	0	Z	NA	
7	8	9	11	12	13	80

PERSONNEL INJURIES

NUMBER	DESCRIPTION				
14	0	0	0	NA	
7	8	9	11	12	80

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION			
16	Z	NA		
7	8	9	10	80

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

8111070270 770517
PDR ADOCK 05000286
S PDR

19

NAME: John M. Makepeace

PHONE: 914-739-8823

RECEIVED
U.S.N.R.C.

MAY 19 1977

OF PRUSSIA

1977 MAY 24 AM 10 40

RECEIVED DOCUMENT
PROCESSING UNIT