

William J. Cahill, Jr.  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N Y 10003  
Telephone (212) 460-3819

June 14, 1976

Re Indian Point Unit No. 3  
Docket No. 50-286  
R.O. -76-3-11(B)

## Regulatory Docket File

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
Region 1  
U.S. Nuclear Regulatory Commission  
King of Prussia, PA 19406



Dear Mr. O'Reilly

In accordance with the requirements of the Technical Specifications to Facility Operating License DPR-64 the attached report of Reportable Occurrence R.O.-76-3-11(B) is submitted. This report fulfills the requirement for a written report within 30 days of a Reportable Occurrence and is in accordance with the format set forth in Regulatory Guide 1.16, Revision 4.

Three copies of this letter and the attachment are enclosed as required.

Very truly yours

William J. Cahill, Jr.  
Vice President

Enc.  
fg



Copy to Director of Nuclear Reactor Regulation  
ATTN: Dr. Ernst Volgenau, Director (30 copies)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director of Nuclear Reactor Regulation  
ATTN: Mr. William G. McDonald, Director (3 copies)  
Office of Management Information and  
Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, N.Y. 10019

6155



(Event Desc. Cont) - was placed in the "pull-out" position, and the lockout relay was reset, Emergency Diesel Generator No. 32 Breaker automatically closed, restoring power to 480V Bus 6A. The overcurrent signal was then reset, normal feed was restored to Bus 6A, and Emergency Diesel Generator No. 32 was shut down and reset for automatic operation.

[R.O. -76-3-11(B)]