

# LICENSEE EVENT REPORT

(PLEASE PRINT ALL REQUIRED INFORMATION)

CONTROL BLOCK: 

--	--	--	--	--	--	--	--	--	--

LICENSEE NAME: 

01	N	Y	I	P	S	3
----	---	---	---	---	---	---

 LICENSE NUMBER: 

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE: 

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE: 

0	3
---	---

CATEGORY: 

01	CONT
----	------

 REPORT TYPE: 

L
---

 REPORT SOURCE: 

L
---

 DOCKET NUMBER: 

0	5	0	-	0	2	8	6
---	---	---	---	---	---	---	---

 EVENT DATE: 

0	5	0	5	7	6
---	---	---	---	---	---

 REPORT DATE: 

0	6	0	3	7	6
---	---	---	---	---	---

### EVENT DESCRIPTION

02 While performing a trip test during a post-maintenance check of a reac-  
tor protection logic channel, Relay V-1, associated with containment  
ventilation isolation functioned only intermittently. The relay was ad-  
justed and operated correctly upon retesting. Examination of similar  
relays in the safeguards logic cabinet was conducted and none were found

SYSTEM CODE: 

I	B
---	---

 CAUSE CODE: 

E
---

 COMPONENT CODE: 

R	E	L	A	Y	X
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER: 

N
---

 COMPONENT MANUFACTURER: 

W	1	2	0
---	---	---	---

 VIOLATION: 

N
---

### CAUSE DESCRIPTION

08 A Westinghouse Type MG-6 relay was found to be misaligned in that the  
pivot point for the operating contacts had shifted. This caused the  
relay to work intermittently.

FACILITY STATUS: 

B
---

 % POWER: 

0	0	0
---	---	---

 OTHER STATUS: 

NA
----

 METHOD OF DISCOVERY: 

B
---

 DISCOVERY DESCRIPTION: 

Surveillance Testing
----------------------

FORM OF ACTIVITY RELEASED: 

Z
---

 CONTENT OF RELEASE: 

Z
---

 AMOUNT OF ACTIVITY: 

NA
----

 LOCATION OF RELEASE: 

NA
----

### PERSONNEL EXPOSURES

NUMBER: 

0	0	0
---	---	---

 TYPE: 

Z
---

 DESCRIPTION: 

NA
----

### PERSONNEL INJURIES

NUMBER: 

0	0	0
---	---	---

 DESCRIPTION: 

NA
----

### PROBABLE CONSEQUENCES

15 NA

### LOSS OR DAMAGE TO FACILITY

TYPE: 

Z
---

 DESCRIPTION: 

NA
----

### PUBLICITY

17 NA

### ADDITIONAL FACTORS

18 (Event Desc. Cont.) - to require adjustment [R.O.-76-3-9(B)].

19 

8111070576 760603
PDR ADOCK 05000286
S PDR

NAME: Austin J. Decker II PHONE: 914-739-8823