

Con
Edison

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003

March 17, 1976

Re: Indian Point Unit No. 3
AEC Docket No. 50-286

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-64, the following confirms the telephone notification to Mr. John Streeter of your office on March 17, 1976 of Reportable Occurrence No. 76-3-2(A). The occurrence is the type defined by Regulatory Guide 1.16, Revision 4, Section C.2.a(3).

During a routine plant status inspection, while at the hot shutdown condition, a slight leak was observed at the nipple to socket connection of vent valve S112 and line No. 351. The connection is located on the discharge line of No. 31 accumulator, downstream of check valve 897A. The plant is currently being cooled down and depressurized to effect repairs.

Very truly yours,

Walter Stein

Walter Stein, Manager
Nuclear Power Generation
Indian Point Station
Buchanan, New York 10511

Copy to: Director of Nuclear Reactor Regulation
Attn: Mr. William F. McDonald, Director (2 copies)
Office of Management Information and
Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8111070646 760317
PDR ADOCK 05000286
S PDR

A04