

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N Y I P S 3 | 2 | 0 0 - 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | \_\_\_\_\_ | 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0 1 | L | 6 | 0 5 0 0 0 2 8 6 | 7 | 0 7 1 0 7 8 | 8 | 0 8 0 9 7 8 | 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 | While shutdown for refueling, performance of Refueling Test, 3PC-R2,  
0 3 | showed Reactor Coolant Loop Flow Transmitter FT-444 and FT-446 to  
0 4 | be outside the required tolerance.  
0 5 |  
0 6 |  
0 7 |  
0 8 |

0 9 | C B | 11 | E | 12 | I N S T R U | 14 | T | 15 | Z | 16  
7 8 9 10 11 12 13 18 19 20

17 | LER/RO REPORT NUMBER | 7 8 | 21 22 | 0 1 6 | 24 26 | 0 3 | 28 29 | L | 30 | 31 | 0 | 32  
REVISION NO.

ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER  
E | 18 | Z | 19 | Z | 20 | Z | 21 | 0 0 0 0 | 22 | N | 23 | N | 24 | N | 25 | F 1 8 0 | 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑰

1 0 | The Foxboro, Model E13DH-SAH1, flow transmitters were found to be  
1 1 | outside the required tolerances and were recalibrated.  
1 2 |  
1 3 |  
1 4 |

1 5 | H | 28 | 0 0 0 | 29 | NA | 44 | B | 31 | Surveillance Test | 32  
7 8 9 10 12 13 44 45 46

1 6 | Z | 33 | Z | 34 | NA | 44 | LOCATION OF RELEASE ⑳

1 7 | 0 0 0 | 37 | Z | 38 | NA | 39  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

1 8 | 0 0 0 | 40 | NA | 41  
PERSONNEL INJURIES NUMBER DESCRIPTION

1 9 | Z | 42 | NA | 43  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

2 0 | N | 44 | NA | 45  
ISSUED DESCRIPTION

8111090731 780801  
PDR ADDOCK 05000286  
S PDR

NRC USE ONLY

NAME OF PREPARER: Neil A. Passman

PHONE: 914-739-8200 X250