

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N | Y | I | P | S | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 6 | 7 | 0 | 6 | 0 | 8 | 7 | 8 | 8 | 0 | 7 | 0 | 8 | 7 | 8 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | While shutdown for refueling, performance of
03 | Refueling Surveillance Test, 3PT-R6 showed the
04 | No. 5 safety valve on the No. 34 Steam
05 | Generator to be outside the required
06 | tolerance.
07 |
08 |

09 | C | C | 11 | E | 12 | B | 13 | V | A | L | V | E | X | 14 | J | 15 | B | 16
7 8 9 10 11 12 13 18 19 20

17 | LER/RO REPORT NUMBER | 7 | 8 | 21 22 | - | 23 | 0 | 1 | 3 | 24 26 | / | 27 | 0 | 3 | 28 29 | L | 30 | - | 31 | 0 | 32

ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS (22) | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
E | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 22 | N | 23 | N | 24 | N | 25 | C | 7 | 1 | 0 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The required pressure setting of 1120 psig on
11 | this Crosly, Model HC65W valve was not
12 | achieved until setting was adjusted.
13 |
14 |

15 | H | 28 | 0 | 0 | 0 | 29 | NA | 30 | B | 31 | Surveillance Test | 32
7 8 9 10 12 13 44 45 46 80

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 10 11 44 45 80

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 11 12 13 80

18 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 11 12 80

19 | Z | 42 | NA | 43
7 8 9 11 12 80

20 | N | 44 | NA | 45 | 8111100069 780705 PDR ADOCK 05000286 S PDR | NRC USE ONLY
7 8 9 10 68 69 80