

POWER AUTHORITY OF THE STATE OF NEW YORK  
INDIAN POINT NO. 3 NUCLEAR POWER PLANT  
P. O. BOX 215 BUCHANAN, N. Y. 10511  
TELEPHONE: 914-739-8200



June 2, 1978  
IP-JWK-1922

Re: Docket No. 50-286

1978 JUN 9 AM 10 38  
U.S. NRC  
DISTRIBUTION SERVICES  
BRANCH  
RECEIVED DISTRIBUTION  
SERVICES UNIT

Mr. Boyce Grier, Director  
Office of Inspection and Enforcement  
Region 1  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

The attached Licensee Event Report LER 78-009/3L-0 is hereby submitted for your information. It should be noted, however, that the Fuel Storage Building charcoal absorber was not required to be operable at the time of testing.

This event was discovered during surveillance testing performed in accordance with Technical Specification 4.5.A.6.c and 4.5.A.6.c (1).

Very truly yours,

*J. P. Bayne*  
J. P. Bayne  
Resident Manager

JWK/rbb

cc: Director of Nuclear Reactor Regulation  
Attn: Mr. William McDonald, Director (2 copies)  
Office of Management Information & Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dr. Ernst Volgenau (40 copies)  
Office of Inspection and Enforcement  
c/o Distribution Services Branch, DDC, ADM  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. George T. Berry  
General Manager and Chief Engineer  
Power Authority of the State of New York  
10 Columbus Circle  
New York, New York 10019

781600317

A002  
5/1

8111100129 780602  
PDR ADCCK 05000286  
S PDR