

John D. O'Toole
Vice President


Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

February 5, 1982

Re: Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

ATTN: Mr. Steven A. Varga, Chief
Operating Reactors Branch #1
Division of Licensing



Dear Mr. Varga:

This letter supplements our December 7, 1981 letter regarding your request that Con Edison commit to certain criteria for future low pressure turbine disc inspection. In that letter it was stated that Con Edison would respond to the request after evaluation of the application of inspection criteria to Indian Point 2 low pressure rotors.

As a result of that evaluation, we agree to use the criteria listed in your October 9, 1981 Safety Evaluation Report during the current and the following fuel cycle. We are working towards the development of a more permanent solution to the disc cracking concern. The results of this effort and the two scheduled inspections will form the basis for evaluating the need to reinspect during subsequent outages.

Should you or your staff have any questions, please contact us.

Very truly yours,

A handwritten signature in cursive script, reading "John D. O'Toole", followed by a horizontal line extending to the right.

cc: Mr. T. Rebelowski,
Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

Adal Sifo

8202160546 820205
PDR ADOCK 05000247
G PDR