

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

December 15, 1982

Re: Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

ATTN: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing

Dear Mr. Varga:

As a result of recent discussions with your staff, information regarding the Indian Point Unit No. 2 Emergency Operating Facility (EOF) is provided in Attachment A to this letter.

Should you or your staff have any further questions, please contact us.

Very truly yours,



attach.

8212270120 821215
PDR ADOCK 05000247
F PDR

A045

Attachment A

RESPONSE TO NRC QUESTIONS
CONCERNING THE EMERGENCY
OPERATIONS FACILITY (EOF)

Question 1 Is the location of the primary EOF on-site?

Response: The EOF is located on-site in the Buchanan Service Center Building approximately 2,000 feet from the reactor building.

Question 2 What is the construction of the primary EOF?

Response: The EOF is of concrete block construction with corrugated metal roof.

Question 3 Does the EOF provide a protection factor of 5?

Response: The present walls provide a protection factor of greater than five; however, the existing roof provides a protection factor of less than five.

Question 4 What is the construction start date for the EOF and is it completed?

Response: Construction of the EOF was started in July, 1980 and is completed.

Question 5 Are there HEPA filters in the EOF ventilation system?

Response: Presently, there are no HEPA filters installed in the existing EOF ventilation system; however, the ventilation system is capable of operating in a recirculation mode with fully closed dampers.

Question 6 Where is the Alternate EOF (AEOF) located?

Response: The AEOF is located at the Eastview Service Center approximately 16 miles SE of the Indian Point Site.

Question 7 What is the construction of the AEOF?

Response: The building in which the AEOF is located is constructed of cinderblock and glass construction, with concrete panel roof.

Question 8

When did construction start on the AEOF structure and is it completed?

Response:

The structure in which the AEOF is located was built prior to 1970. The AEOF is completed.