

John D. O'Toole
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003
Telephone (212) 460-2533

November 29, 1985

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Hugh L. Thompson, Jr., Director
Division of PWR Licensing-A
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Thompson:


In accordance with the Attachment to your letter of March 11, 1985, regarding NUREG-0737, Supplement 1, we are submitting a schedule for implementation of the Regulatory Guide 1.97 modifications identified in our August 30, 1985 letter to you.

It is our intention to complete all modifications identified in Attachment A, Sections 2.0 and 3.0, of that letter, by the end of the second refueling outage after the 1986 refueling outage for Indian Point Unit No. 2. Con Edison reserves the right to revise this commitment, if necessary, following the issuance of a Safety Evaluation Report (SER) by your staff, or due to re-examination of the IP-2 modification schedule within the context of the priorities of all requirements and Con Edison resources and operating schedules (i.e., "Integrated Implementation Schedule").

Should you or your staff have any questions on this matter, do not hesitate to call us.

8512060299 851129
PDR ADOCK 05000247
F PDR

Very truly yours,



cc: Mr. Steven A. Varga, Project Director
PWR Project Directorate No. 3
Division of PWR Licensing-A
Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Office of Senior Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York, 10511

A003
11/10