

Stephen B. Bram
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 737-8116

April 22, 1988

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

SUBJECT: 1987 Refueling Outage Inservice Inspection and Inservice Test
Programs Summary Report


Inservice inspections and tests of primary-side and secondary-side components and piping, reactor vessel and steam generators were performed during the 1987 refueling outage pursuant to Indian Point Unit No. 2's ISI and IST programs, and pursuant to section 4.2 of the Technical Specifications. These inspections and tests complete the first period of the second ten-year inservice inspection and test interval.

A summary of the work performed, and the areas subject to examination and test, is provided in Attachments I and II. The detailed data is available for on-site review. Furthermore, Form NIS-1 entitled "Owners Data Report For Inservice Inspections" is contained in Attachment III.

Pursuant to the provisions of the Indian Point Unit No. 2 Technical Specifications, Section 4.2.G, Item 7.2, we submitted our report entitled "Indian Point Unit 2 Reactor Vessel Special Inspection" on November 25, 1987. That report described the special inspections performed on the Indian Point Unit 2 reactor vessel during the 1987 refueling outage. In addition, our February 15, 1988 letter to you transmitted our Steam Generator Inservice Inspection Report which detailed our girth weld inspections and repairs. That report details the repair program and our conclusions regarding the cause of the indications. That letter supplemented our submittals of December 11, 1987, December 23, 1987 and January 15, 1988 regarding the linear indications in the Indian Point No. 2 steam generator shell-to-cone weldment as determined by inspections conducted during the recent refueling outage.

Should you or your staff have any further questions, please contact us.

Very truly yours,



Attachments

8805020052 880422
PDR ADDCK 05000247
P DCD

A047
11

cc: Mr. William Russell
Regional Administrator - Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406-1498

Ms. Marylee M. Slosson, Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
U.S. Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 38
Buchanan, NY 10511