

Stephen B. Bram
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 737-8116

July 26, 1989

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555


SUBJECT: Steam Generator Tube Inservice Inspection Program
1989 Inspection Program Results

The results of steam generator tube inspections as conducted at Indian Point Unit No. 2 (IP-2) during the recently concluded refueling outage are reported in Attachment I to this letter pursuant to IP-2 Technical Specification 4.13. The inspection program was described in our December 28, 1988 letter and approved by NRC by letter dated February 16, 1989. Additional information on the program was transmitted via a letter dated February 21, 1989.

Based upon the results of the most recent inspections, we have concluded that the next steam generator tube examinations should be conducted at the time of the next refueling outage. We request that you review the enclosed report and approve our proposed examination schedule in accordance with Technical Specification Section 4.13.C.5.

Should you or your staff have any questions regarding this matter, please contact Mr. Jude G. Del Percio, Manager, Regulatory Affairs and Safety Assessment.

Very truly yours,



Attachment

8908080040 890726
PDR ADOCK 05000247
Q PNU

A047
1/1

cc: Mr. William Russell
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406-1498

Mr. Donald S. Brinkman, Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511