

Consolidated Edison Company of New York, Inc. Indian Point Station Broadway & Bleakley Avenue Buchanan, NY 10511 Telephone (914) 737-8116

August 19, 1988

Re:

Indian Point Unit No. 2 Docket No. 50-247

Document Control Desk
U.S. Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

SUBJECT: Inoperable Fire Barriers Reported on May 24, 1988

In accordance with Technical Specification 3.13.C.2.b, a 30-day report on inoperable fire barriers discovered during testing was submitted on May 24, 1988 because repairs could not be completed within the time allowed. This letter provides the status of the repairs.

It was previously reported that the inoperable fire barriers were discovered during tests performed on April 19, April 27 and May 5, 1988. It has since been determined the May 5 test did not involve Technical Specification fire barriers.

It was also reported an hourly fire watch had been established and that repairs were to be completed by July 31, 1988. Although repairs were initiated in advance of this date, delays were encountered and the repairs, with one exception, were completed by August 12, 1988. Evaluation of plant conditions during repairs indicated the fire barrier associated with the disconnect box for the containment spray logic cannot be repaired until the Unit is in a cold shutdown of sufficient duration to allow repair. The hourly fire watch will continue until this fire barrier is restored to operable status.

If you or your staff have any questions, please contact us.

Very truly yours,

TEX?

CC: Mr. William Russell
 Regional Administrator - Region I
 U.S. Nuclear Regulatory Commission
 475 Allendale Road
 King of Prussia, PA 19406-1498

Ms. Marylee M. Slosson, Project Manager Project Directorate I-1 Division of Reactor Projects I/II U.S. Nuclear Regulatory Commission Mail Stop 14B-2 Washington, DC 20555

Senior Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 38 Buchanan, NY 10511