Consolidated Edison Company of New York, Inc. Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 737-8116

June 23, 1990

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk US Nuclear Regulatory Commission Mail Station P1-137 Washington, DC 20555

SUBJECT: 30-Day Report, Inoperable Fire Barrier

On May 18, 1990, with Indian Point Unit No. 2 in cold shutdown, during an inspection of fire barriers it was discovered that the penetration fire barrier between the Primary Auxiliary Building and the electrical tunnel was outside operating specifications.

The Technical Specifications Section 2.13 requires that a 30 day report regarding inoperable fire barriers be submitted. During the period of inoperability, compensatory action, in the form of an hourly fire watch is being performed.

A site visit by fire barrier repair contractors has been scheduled to restore promptly the fire barrier to operational condition.

This report fulfills the reporting requirements for the inoperable penetration fire barrier.

Should you have any questions, please contact Mr. Charles W. Jackson, Manager, Nuclear Safety and Licensing.

Very truly yours,

cc: Mr. Thomas T. Martin
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Donald S. Brinkman, Senior Project Manager Project Directorate I-1 Division of Reactor Projects I/II US Nuclear Regulatory Commission Mail Stop 14B-2 Washington, DC 20555

Senior Resident Inspector US Nuclear Regulatory Commission PO Box 38 Buchanan, NY 10511

1E22