

Stephen B. Bram
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 737-8116

August 15, 1990

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Thomas T. Martin
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

SUBJECT: Notification of Inoperable Fire Pump


Section 3.13.A.2 of the Indian Point Unit No. 2 Technical Specifications provides that one motor driven high pressure water fire protection system pump may be out of service for a period not to exceed 7 days, and specifies that if the equipment cannot be returned to service within the 7 days, a Special Report must be submitted within 30 days.

On July 19, 1990, the No. 12 Fire Booster pump was taken out of service to repair a faulty discharge check valve, FP-91, located immediately downstream of the pump. It was determined that the valve had to be replaced, and difficulty was experienced in obtaining a valve that met the material specifications of the valve to be replaced. On July 26, 1990, the unit's No. 12 Fire Booster Pump was out of service for a period that exceeded the 7 days. On July 29, 1990 the Fire Booster Pump was returned to service.

This letter satisfies the 30 day report requirement.

Should you or your staff have any questions regarding this matter, please contact Mr. Charles W. Jackson, Manager, Nuclear Safety and Licensing.

Very truly yours,



cc: Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

Mr. Donald S. Brinkman, Senior Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511

9008230067 900815
FOR ADCK 05000247
S PDC

IE22
110