

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10611
914 736.8001



**New York Power
Authority**

Robert J. Barrett
Site Executive Officer

June 11, 1998
IPN-98-068

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
Generic Letter 93-04 Close-Out Actions

Reference: Letter from Nuclear Regulatory Commission to New York Power
Authority, dated November 23, 1994, "Closure of Generic Letter 93-04,
Rod Control System Failure and Withdrawal of Rod Control Cluster
Assemblies - Indian Point Nuclear Generating Unit No. 3"

Dear Sir:

The purpose of this letter is to provide confirmation of the actions implemented at Indian Point 3 in response to Generic Letter 93-04, "Rod Control System Failure and Withdrawal of Rod Cluster Control Assemblies." The referenced letter stated the actions we committed to in response to GL 93-04 were found acceptable.

NRC Inspection Report 50-286/94-31, dated March 13, 1995, noted that only two (2) committed actions regarding GL 93-04 remained to be completed. The first action was to perform post-modification verification testing of control rod drive mechanism current profiles using actual control rod motion prior to startup from the 1995 outage. This was completed prior to startup. The second action was to perform testing to identify failure in the rod control system during every refueling outage there after. The first refueling outage (RO-9) since the 1995 startup was conducted in the Spring of 1997. This testing was successfully performed during RO-9 and will be scheduled to be performed during future refueling outages. This completes the actions and reporting requirements for Generic Letter 93-04.

If you have any questions regarding this matter, please contact Mr. K. Peters.

Very truly yours,


Robert Barrett
Site Executive Officer

1/0
A030

9806190008 980611
PDR ADOCK 05000286
P PDR