

Stephen E. Quinn
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340

August 21, 1995

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

SUBJECT: Follow up on Generic Letter 93-04, "Rod Control System Failure and Withdrawal of Rod Cluster Control Assemblies, 10 CFR 50.54(f)," Indian Point Nuclear Generating Station Unit No. 2

As committed to in our December 22, 1994 letter, Con Edison has implemented a current order surveillance test to be performed during every refueling outage at our Indian Point Unit 2 plant. The surveillance test was performed during our recently completed refueling outage. The test results verify that no failures that result in corrupted current orders, including Salem Unit 2 type failures, exist in the Rod Control system.

In accordance with Generic Letter 93-04, Con Edison will continue to keep the NRC informed of its activities in this area.

Should you have any questions regarding this matter, please contact Mr. Charles W. Jackson, Manager, Nuclear Safety and Licensing.

Very truly yours,

Thomas Schmeiser

cc: Mr. Thomas T. Martin
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Francis J. Williams, Jr., Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511

9508290242 950821
PDR ADDCK 05000247
P PDR

AO30 1/0