

Paul H. Kinkel
Vice President

Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, NY 10511
Telephone (914) 734-5340
Fax: (914) 734-5923

October 9, 1997

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555-0001

SUBJECT: 1997 Refueling Outage Inservice Inspection Program Summary
Report - Second Outage, First Period, Third Interval.

Pursuant to the requirements of Indian Point Unit No. 2 Technical Specification Section 4.2.2, inspections of the primary and secondary side components (the reactor head, pressurizer, steam generator, regenerative heat exchanger, reactor coolant pump, residual heat removal heat exchanger, and piping and supports) were performed during the 1997 refueling outage. These inspections, which are within the Inservice Inspection Program, satisfy the requirements for the second outage of the first period of the third interval.

A report summarizing the inspections performed, the areas subject to examination, Form NIS-1, "Owners Report For Inservice Inspections," and Form NIS-2, "Owners Report For Repairs and Replacement," is attached. Additional information, which supports this summary report, is available onsite for review.

Should you or your staff have any questions regarding this matter, please contact Mr. Charles W. Jackson, Manager, Nuclear Safety & Licensing.

Very truly yours,

Paul H. Kinkel

1/1

Attachment

9710150184 971009
PDR ADOCK 05000247
Q PDR

100010

ADCF



cc: Mr. Hubert J. Miller
Regional Administrator-Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Jefferey F. Harold, Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511