

Consolidated Edison Company of New York, Inc. Indian Point Station Broadway & Bleakley Avenue Buchanan, NY 10511 Telephone (914) 734-5340 Fax: (914) 734-5923

May 4, 1998

Re:

Indian Point Unit No. 2

Docket No. 50-247

Document Control Desk US Nuclear Regulatory Commission Mail Station P1-137 Washington, DC 20555

Subject:

Generic Letter 93-04, "Rod Control System Failure and Withdrawal

of Rod Control Cluster Assemblies"

References:

Letter Paul H. Kinkel (Con Edison) to Document Control Desk,

December 11, 1997

Letter Paul H. Kinkel (Con Edison) to Document Control Desk,

April 15, 1998

This letter supplements the above-referenced letters to confirm that during our 1997 refueling outage which ended July 11, 1997, Indian Point Unit No. 2 implemented the current order timing modification and the current order surveillance test recommended by the Westinghouse Owners Group.

Should you have any questions please contact Mr. Charles W. Jackson, Manager Nuclear Safety and Licensing, at (914) 734-5127.

Very truly yours,

Paul 11 Il

A030/0

180096

cc: Mr. Hubert J. Miller
Regional Administrator-Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Jefferey F. Harold, Project Manager Project Directorate I-1 Division of Reactor Projects I/II US Nuclear Regulatory Commission Mail Stop 14B-2 Washington, DC 20555

Senior Resident Inspector US Nuclear Regulatory Commission PO Box 38 Buchanan, NY 10511