

Indian Point 3
Nuclear Power Plant
P.O. Box 215
Buchanan, New York 10511
914 736.8001



L. M. Hill
Site Executive Officer

February 14, 1996
IPN-96-012


U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

SUBJECT: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
License No. DPR-64
Licensee Event Report # 95-024-01
**Technical Specification Required Shutdown due to Service Water
Containment Isolation Valve Leakage Caused by Corrosion**

Dear Sir:

The attached Licensee Event Report (LER) 95-024-01 is hereby submitted as required by 10CFR50.73. This event is of the type defined in 10CFR50.73(a)(2)(i)(A). This supplement reports different valve failure mechanisms as a result of further analysis. Also, attached is the commitment made by the Authority in this LER.

Very truly yours,


L. M. Hill
Site Executive Officer
Indian Point 3 Nuclear Power Plant

Attachment

cc: See next page

210034

9602210006 960214
PDR ADOCK 05000286
S PDR

IE22
11

cc: Mr. Thomas T. Martin
Regional Administrator
Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

INPO Record Center
700 Galleria Parkway
Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission
Resident Inspectors' Office
Indian Point 3 Nuclear Power Plant

Attachment 1
List of Commitments

Number	Commitment	Due
IPN-96-012-01	Revise AP-58 to incorporate the increased scope of inspecting selected valves.	April 19, 1996