Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511 914 736.8001



Robert J. Barrett
Site Executive Officer

July 30, 1997 IPN-97-103

U.S. Núclear Regulatory Commission ATTN: Document Control Center Washington, D.C. 20555

SUBJECT:

Indian Point 3 Nuclear Power Plant

Docket No. 50-286 License No. DPR-64

Licensee Event Report 97-012-00

A Common Condition Causing Multiple Core Exit Thermocouples to be Inoperable During Postulated Accident Conditions Due to

Moisture Intrusion, an Original Manufacturer Defect

Dear Sir:

The attached Licensee Event Report (LER) 97-012-00 is submitted as required by 10 CFR 50.73. This event is of the type defined in 10 CFR 50.73 (a)(2)(vii).

There are no commitments being made in this LER.

Very truly yours,

Robert J. Barrett

Site Executive Officer

Indian Point 3 Nuclear Power Plant

Attachment

cc: see next page

Terr

9708080057 970730 PDR ADOCK 05000286 S PDR



Docket No. 50-286 IPN-97-103 Page 2 of 2

cc: Mr. Hubert J. Miller
Regional Administrator
Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

INPO Record Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission Resident Inspectors' Office Indian Point 3 Nuclear Power Plant