Indian Point 3 Nuclear Power Plant P.O. Box 215 Buchanan, New York 10511 914 736 8001

NewYorkPower Authority

January 16, 1998 IPN-98-005 Robert J. Barrett Site Executive Officer

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

SUBJECT:

Indian Point 3 Nuclear Power Plant Docket No. 50-286 License No. DPR-64 Licensee Event Report # 97-032-00

480 Volt Bus Inoperable Due to A Failure of the 32 Residual Heat Removal Pump Circuit Breaker To Open; A Condition Prohibited by Technical Specification

Dear Sir:

The attached Licensee Event Report (LER) 97-032-00 is hereby submitted as required by 10 CFR 50.73. This event is of the type defined in 10 CFR 50.73 (a)(2)(i)(B).

Also attached are the commitments made by the Authority in this LER.

630

Very truly yours, ober

Robert J. Barrett Site Executive Officer Indian Point 3 Nuclear Power Plant

cc: See next page 9801280072 980116 PDR ADDCK 05000284 S PDR 400020

Docket No. 50-286 IPN-98-005 Page 2 of 2

Mr. Hubert J. Miller Regional Administrator Region I U. S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, Pennsylvania 19406-1415

. ;.

INPO Record Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

U.S. Nuclear Regulatory Commission Resident Inspectors' Office Indian Point 3 Nuclear Power Plant

cc:



Docket No. 50-286 IPN-98-005 Attachment I Page 1 of 1

..

N 1. -

Commitment List

a an an ann an Allan a' an ann an Allan an Allan ann an Allan ann an Allan an A

Number	Commitment	Due
IPN-98-005-01	Perform a EFE/root cause investigation for the failure of the 32 RHR pump breaker (A1033).	March 6, 1998
IPN-98-005-02	The Authority will supplement LER 97-032 after completion of a review of the breaker EFE/root cause investigation.	April 17, 1998