

August 18, 1995



Consolidated Edison Company of New York, Inc.
Indian Point Station
Broadway & Bleakley Avenue
Buchanan, New York 10511-1099

NYSDEC - Division of Water
SPDES Compliance Information Section
Bureau of Water Compliance Programs
50 Wolf Road - Room 320
Albany, New York 12233-3506

Re: Monthly Discharge Monitoring Report
Permit #0004472
Con Edison Indian Point Units 1 & 2
New York Power Authority Indian Point Unit 3

Gentlemen:

Enclosed are the Discharge Monitoring Reports (DMR) for the month of July 1995. A Report of Noncompliance Event is attached.

Explanation for deviations from the permitted circulator flows are forwarded to the Department of Environmental Conservation as they occur and, therefore, are not enclosed.

If you have any questions regarding this submission, please contact Mr. Reynolds Burns of Con Edison at (914)734-5605 or Mr. Mathew Kerns of New York Power Authority at (914)736-8452.

Very truly yours,

Thomas Schmeiser
Plant Manager
Indian Point Station
Con Edison Units 1 & 2

Attachment

/kj

9603210410 960314
PDR ADDCK 05000286
S PDR

SECTION 1

New York State Department of Environmental Conservation
Division of Water



Report of Noncompliance Event

To: DEC Water Contact Cesare Manfredi DEC Region: 3

Report Type: 5 Day Permit Violation Order Violation Anticipated Noncompliance Bypass/Overflow

SECTION 2

SPDES #: NY- 0004472 Facility: New York Power Authority - IP3

Date of noncompliance: 07/19/95 Location (Outfall, Treatment Unit, or Pump Station): Outfall 001J

Description of noncompliance(s) and cause(s): During a weekly turbine hall floor drain inspection oil was found in a floor drain.

Has event ceased? (Yes) (No) If so, when? 07-19-95 Was event due to plant upset? (Yes) (No) SPDES limits violated? (Yes) (No)

Start date, time of event: 07/19/95, 20:50 (AM) (PM) End date, time of event: 07/19/95, 21:30 (AM) (PM)

Date, time oral notification made to DEC? / N/A (AM) (PM) DEC Official contacted: N/A

Immediate corrective actions: The area was cleaned and the floor drain was cleaned. Oil absorbant material was placed in the area where necessary. This event was mitigated due to this floor drain going to a sump that is equipped with an oil skimmer.

Preventive (long term) corrective actions: Housekeeping and cleanliness of the turbine building has been intensified.

SECTION 3

Complete this section if event was a bypass:

Bypass amount: _____ Was prior DEC authorization received for this event? (Yes) (No)

DEC Official contacted: _____ Date of DEC approval: _____

Describe event in "Description of noncompliance and cause" area in Section 2. Detail the start and end dates and times in Section 2 also.

SECTION 4

Facility Representative: David O'Brien Title: Licensing Coord. Date: 08/23/95

Phone #: (914) 736-8017 Fax #: (914) 736-8769