

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Sentinel Imaging, LLC 29240 Buckingham Street Livonia, Michigan 48154 REPORT NUMBER(S) 2010-001	2. NRC/REGIONAL OFFICE Region III U.S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, Illinois 60532-4351
--	--

3. DOCKET NUMBER(S) 030-38088	4. LICENSEE NUMBER(S) 21-32756-01	5. DATE(S) OF INSPECTION March 3, 2010
----------------------------------	--------------------------------------	---

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Geoffrey M. Warren		3/10/10

BA

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE Sentinel Imaging, LLC REPORT NUMBER(S) 2010-001		2. NRC/REGIONAL OFFICE NRC Region III 2443 Warrenville Road, Suite 210 Lisle, Illinois 60532-4351	
3. DOCKET NUMBER(S) 030-38088	4. LICENSE NUMBER(S) 21-32756-01	5. DATE(S) OF INSPECTION March 3, 2010	
6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS 03.01 – 03.08		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02121	2. PRIORITY 5	3. LICENSEE CONTACT Laura T. Smith, M.S., Consultant	4. TELEPHONE NUMBER 586-716-8885
-----------------------------	------------------	---	-------------------------------------

Main Office Inspection Next Inspection Date: March 2011

Field Office _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

This was an initial inspection of activities performed under this license.

The licensee's intention was to provide diagnostic nuclear medicine services to a medical clinic, but the intended clinic had ceased operations before the licensee could begin offering services. As such, the licensee had not begun licensed operations, except that the licensee had received a 100 microcurie technetium-99m dose for calibration of the camera. The licensee hoped to close this location and open another location to provide nuclear medicine services. The consultant had performed a closeout survey at this facility and found no contamination; she intended to submit this survey to NRC to release this facility.

The next inspection date is set at one year because the licensee had not begun licensed operations.

Performance Observations

The inspector performed confirmatory closeout surveys of areas where the technetium-99m dose could have been used, and found no evidence of contamination.

BB