




PSEG Power, LLC
PSEG Site ESPA
Part 2, Site Safety Analysis Report

Flow Rates at the New Plant Location
Following Failure of the Pepacton and
Cannonsville Dams

Figure 2.4.4-4

Rev. 0