



PSEG Power, LLC

PSEG Site ESPA
Part 2, Site Safety Analysis Report

Synthetic Modulus and Damping
Degradation Curves for Soil
Layers 6 through 8

FIGURE 2.5.2-39

Rev 0