

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Mid-American Inspection Services, Inc.
Gaylord, MI ; Manistee, MI

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road
Suite 210
Lisle, Illinois 60532-4351

REPORT NUMBER(S) 2010-001

3. DOCKET NUMBER(S)

030-31160

4. LICENSEE NUMBER(S)

21-26060-01

5. DATE(S) OF INSPECTION

6/23 & 25/10

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:


- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Michael M LaFrance		7/8/10

gpb

**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Mid American Inspection Services, Inc. REPORT NUMBER(S) 2010-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-31160	4. LICENSE NUMBER(S) 21-26060-01	5. DATE(S) OF INSPECTION 6/23 and 25/2010	
6. INSPECTION PROCEDURES USED		7. INSPECTION FOCUS AREAS 03.01 – 03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3320	2. PRIORITY 1	3. LICENSEE CONTACT Terry Wilkins – Owner/RSO	4. TELEPHONE NUMBER 989-732-8059
----------------------------	------------------	--	-------------------------------------

Main Office Inspection Next Inspection Date: 6/2011

Field Office

Temporary Job Site Inspection Gaylord, MI and Manistee, MI

PROGRAM SCOPE

The licensee was an industrial radiographer located in Gaylord, Michigan. The licensee was authorized for temporary job sites at any location within NRC jurisdiction. The licensee has numerous radiographic camera's and performs licensed operations Monday through Friday and sometimes on weekends. The licensee also possesses a Cs-137 source used to calibrate survey instruments. The licensee had 12 qualified radiographers at the time of the inspection.

Performance Observations

This was a routine safety inspection of licensed activities. The inspector observed licensee staff perform radiographic operations at two temporary job sites. The inspector noted that all radiographic equipment was functioning properly, the licensee personnel possessed and used all required dosimetry, all radiographic surveys were performed, all boundaries were set up and posted and security of the device was maintained during the review. The inspector performed independent radiation measurements; no abnormal levels were identified. The inspector did a comparison side-by-side radiation surveys between licensee and NRC survey equipment; readings were within +/- 20%. The inspector reviewed licensee's documentation which included utilization logs, dosimetry records, inventory and leak test records; no abnormal issues were identified. The inspector noted that the licensee had submitted NSTS documentation to NRC as required and had just received authorization to transmit the information electronically.

The results of the Security inspection was documented in Inspection Report No. 030-31160/2010-002.

8/17