www.exeloncorp.com

Oyster Creek Generating Station Route 9 South PO Box 388 Forked River, NJ 08731

10 CFR 50.2

Exelon

Nuclear

August 2, 2010

RA-10-062

US Nuclear Regulatory Commission Document Control Desk Washington, DC: 20555-0001

> Oyster Creek Nuclear Generating Station Renewed Facility Operating License No. DPR-16 NRC Docket No. 50-219

Subject: Sea Turtle Incidental Take Reports 2010-4 and 2010-5

The attached reports provide detailed information regarding the recent incidental takes of one live and one dead juvenile Kemp's ridley sea turtles at Oyster Creek Nuclear Generating Station (OCNGS) on July 3 and July 9, 2010. OCNGS has reached 50% of the 2006 Biological Opinion Incidental Take Statement limit of eight sea turtles. Please note that the MMSC stranding report or the necropsy for the July 9th turtle are not available at this time but will be submitted for the annual summary of incidental takes.

If you have any questions or require additional information, please do not hesitate to contact Malcolm Browne at (609) 971-4124.

Sincerely,

IM Onpha

Peter M. Orphanos Plant Manager Oyster Creek Nuclear Generating Station

Enclosures:

Incidental Take Reports 2010-4 and 2010-5 with photographs and diagram MMSC Stranding Report MMSC-10-132

cc: Julie Crocker

U.S. Department of Commerce National Oceanic & Atmospheric Administration National Marine Fisheries Service Northeast Region Protected Resources Division One Blackburn Drive Gloucester, MA 01930

Pasquale Scida U.S. Department of Commerce National Oceanic & Atmospheric Administration National Marine Fisheries Service Northeast Region Protected Resources Division One Blackburn Drive Gloucester, MA 01930

Administrator, Region 1 US Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

G. Edward Miller Senior Project Manager US Nuclear Regulatory Commission Mail Stop 8-B1 Washington, DC 20555

Jeff Kulp Senior Resident Inspector Oyster Creek Generating Station PO Box 388 Forked River, NJ 08731

Jeanette Bowers-Altman NJ Department of Environmental Protection Division of Fish, Game, and Wildlife P.O. Box 400 Trenton, NJ 08625-0400

Regulatory Assurance File No. 10062

	Incidental Take 2010-4	Incidental Take 2010-5
OPERATIONS DEPARTMENT:		
Observer's full name:	Joe Liquori	George Sherrier
Reporter's full name:	Andrew Zuchowski	David Schaffer
Species Identification (Key attached):	Kemp's ridley	Kemp's ridley
Site of Impingement (CWS or DWS):	cws	DWS
Bay Number:	5	6
Date animal observed:	3-Jul-10	9-Jul-10
Time animal observed:	0:36	0:25
Date animal collected:	3-Jul-10	9-Jul-10
Time animal collected:	0:40	0:25
CONDITIONS AT COLLECTION:		
Tidal Stage:	Flood Tide	Ebb Tide
Cloud conditions:	Clear	Clear
Precipitation:	None	None
Intake water temperature:	78.6°F	87.9°F
Other conditions	Heavy debris loading, wind 4.8 mph at 247.9 degrees	Heavy debris loading, wind 2.7 mph at 165 degrees
Number of CW pumps running:		4
Number of DW pumps running:	2	2
Reactor power level at observation:	100%	78%
Reactor power previous 48- hours:	100%	100%
Date of last screen inspection:	2-Jul-10	8-Jul-10
Time of last screen inspection:	21:47:00 AM	17:10:00 AM
ENVIRONMENTAL DEPARTMENT:		
Date Brigatine MMSC contacted:	3-Jul-10	9-Jul-10
Time Brigatine MMSC contacted:	1:15	1:40
Date Animal picked up by MMSC:	3-Jul-10	9-Jul-10
Time Animal picked up by MMSC:	2:15	3:30
State of animal when first observed:	Alive	Unresponsive

		· .
	Incidental Take 2010-4	Incidental Take 2010-5
State of animal when collected:	Good condition with normal behaviour, small scratches on carapace, no other visible signs of injury	Dead
State of animal when picked	Sea turtle healthy and exhibiting normal behavior; no injuries noted; few small scratches on carapace.	Turtle had scrapes on shell (minor) underside had small puncture wound in middle of chest. Dead.
State of animal arriving at MMSC:	Several old scrapes and injuries on the plastron. A few minor scrapes on the carapace. Approx 1-inch wound under LFF near joint and approx 1/2-inch wound just above joint. Approx 1/2-inch wound under RFF. All wounds are old and partially healed. This turtle was active and eating well.	Dead
Final disposition of animal:	Tagged and released alive at the north end of Brigatine 7/9/10. Tagged RFF metal tag # SSL133 PIT tagged LFF # 4A2408150C	Transferred to MMSC Brigantine, NJ
Carapace Length - Curved	32.5 cm	34.3 cm
Carapace Length - Straight	31.8 cm	33 cm
Carapace Width - Curved:	33 cm	31.8 cm
Carapace Width - Straight:	28.9 cm	30.5 cm
Weight - Ibs (kgs)	10.2 lbs	13 lbs (est.)
Existing Tag Number	no tag	no tag
Photograph attached	yes	yes
Diagram of wounds, abnormalities, tag locations attached	Stranding Report MMSC-10-131	yes
Description of Animal	Juvenile Kemp's ridley of undeterminate sex	Juvenile Kemp's ridley of undeterminate sex

z in stand


р. М. с. – ¹. .


SEA TURTLE STRANDING AND SALVAGE NETWORK - STRANDING REPORT


~, ·

Area code/Phone number(6	Last <u>Deerr</u> anding Center Brigantine Blvd., Brigantine, NJ 08203 09) 266-0538 STRANDING LOCATION: Offshore	
□ UN = Unidentified Check Unidentified if not positive. Do Not Guess. Carcass necropsied? □Yes⊠No Photos taken? ⊠Yes □No Species verified by coordinator? ☑ Yes □ No SEX: ☑ Undetermined □ Female □ Male Does tail extend beyond carapace? □ Yes; how far? □cm/□in ☑ No How was sex determined? □ Necropsy	CONDITION: (check one) ○ ○ 1 = Fresh dead ○ 2 = Moderately decomposed ○ 3 = Severely decomposed ○ 4 = Dried carcass. 5 = Skeleton, bones only TAGS: Contact coordinator before disposing of any tagged animall! Checked for flipper tags? ○ Yes ○ No Check all 4 flippers. If found, record tag number(s) / tag location / return address PIT tag scan? ○ Yes ○ No If found, record number / tag location	FINAL DISPOSITION: (check.) 1 = Left on beach where found; painted? Yes* No(5) 2 = Buried: on beach / off beach; carcass painted before buried?Yes* No 3 = Salvaged: all / part(s), what/why? 4 = Pulled up on beach/dune; painted?Yes* No 6 = Alive, released 7 = Alive, taken to rehab: facility, where? MMSC B = Left floating, not recovered; painted?Yes*No 9 = Disposition unknown; explain *If painted, what color?
Tail length (adult only)	Coded wire tag scan? Yes No If positive response, record location (flipper) <u>Unable to check for</u> Checked for living tag? Yes No If found, record location (scute number & side))	CARAPACE MEASUREMENTS: (see drawing) Using calipers Circle unit Straight length (NOTCH-TIP) 31.8 Circle unit Minimum length (NOTCH-NOTCH)
Posterior Marginal TIP NOTCH	or debris entanglement, propeller damagenetic propeller damagenetic provide a second structure of the second secon	T IMPINGEMENT; Several old scrapes and injuries on apace; Approx. 1 inch wound under LFF near the joint is joint; an approx. 1/2 inch wound under the RFF; All rtle was active and eating well. There were no problems the north end of Brigantine on 7/09/2010.

.







276 C 11

ational Marine Fisheries Service, Northeast Reg Protected Resources Division Attention: Endangered Species Coordinator One Blackburn Drive Gloucester, MA 01930