


Technical Approach Condition Assessment – IR Scan in Buttress 3 – 4 Area



P/246