U.S. NUCLEAR REGULATORY COMMISSION 10-2003) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
LICENSEE/LOCATION INSPECTED: ITER Corp., dba Mechanical Integrity Solutions Doral Bank Plaza 33 Resolution Street, 4 th Floor, Suite 401 San Juan, Puerto Rico 00920			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415				
REPORT Nos 2010-001			King of Frussia, Fellisylvania 19400-1415				
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(5. DATE(S) OF INSPECTION			CTION	
030-36190		52-25615-01			October 4, 5, 14 & 29, 2010		
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X							
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.							
Title		Printed Name			Signature	Date	
LICENSEE'S REPRESENTATIVE					,		
NRC INSPECTOR	Scott Wils	son		MARAN	na	10/29/2010	
BRANCH CHIEF	Marie Mil	Marie Miller		Craix Sinder For MM		10/29/2010	
591M PART 1 (RI Rev. 10//2010)		G:\Wo	rdDocs\Current	\Insp Recerd\F	R52-25615-01.2010-00°	1.591M-Part1.doc	
SUNSI Review Completed By:		Scott Wilson	_		X Public [X Non-Sensitive	