

NOV 15 2010



LR-N10-0410

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

**Salem Generating Stations Units 1 and 2
Facility Operating License DPR-70 and DPR-75
Docket Nos. 50-272 AND 50-311**

Subject: **Correction to Owners Activity Reports**

References: Salem Nuclear Generating Station, Unit Nos. 1 and 2
NRC Integrated Inspection Report **05000272/2010003** and
05000311/2010003 dated August 10, 2010

In the referenced Integrated Inspection Report, PSEG Nuclear LLC received a Non Cited Violation for not performing the required inservice inspection provided by the ASME Code, Section XI, intended to demonstrate the structural integrity of a portion of safety related Auxiliary Feedwater buried piping since 1988. Therefore, Owners Activity Reports submitted up until this violation, which had certified that examinations and test meet the inspection plan as required by ASME Code, Section XI, which would have included these buried pipe portions, were not accurate.

Salem Unit 1 buried piping (i.e., Auxiliary Feedwater, Service Water and Control Air Piping) was tested satisfactorily in the spring 2010 outage. Salem Unit 2 buried piping will be inspected/tested in the spring 2011 outage.

This letter is being submitted to acknowledge this inaccuracy in reporting; however, PSEG does not plan to submit revised owners group activity reports.

There are no commitments contained in this letter. If you have any questions regarding this matter, please contact Jeff Keenan, Manager – Licensing, at 856-339-5429.

Sincerely,


Jeff Keenan
Manager - Licensing

A047
NRC

Document Control Desk
LR-N10-0410

C Mr. W. Dean, NRC Regional Administrator - Region I,
Mr. R. Ennis, USNRC, Licensing Project Manager - Salem
USNRC Senior Resident Inspector - Salem (X24)

Mr. P. Mulligan, Manager IV

PSEG Commitment Coordinator - Salem