

Monticello Nuclear Generating Station
Outline Submission Comments

Admin JPM 1 – The RO/SRO JPM appears to be the same JPM for both license levels.

Admin JPM 2 – The RO/SRO JPM appears to be the same JPM for both license levels.

Admin JPM 4 – The RO/SRO JPM appears to be the same JM for both license levels.

Scenario 1 – Add the RCIC failure in event 3 so we know it is unavailable during the major transient. Add the feed pump trip after the start of the major transient.

Scenario 4 – add DW spray failure to the list of malfunctions so we are aware of their failure during the major transient.

There is no low power scenario.;