


NRC FORM 591M PART 1 <small>(4-2008) 10 CFR 2.201</small>		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: EHM Engineers, Inc. 621 North College Road, Suite 100 Twin Falls, Idaho 83301		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125	
REPORT NO: 2010-001			
3. DOCKET NUMBER 030-32261	4. LICENSE NUMBER 11-27304-01	5. DATE OF INSPECTION December 7, 2010	
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:			
<input type="checkbox"/> 1. Based on the inspection findings, no violations were identified.			
<input checked="" type="checkbox"/> 2. Previous violation(s) closed.			
<input type="checkbox"/> 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.			
<input type="checkbox"/> Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):			
<input checked="" type="checkbox"/> 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.			
Title 10 CFR 71.5(a) requires, in part, that each licensee who transports licensed material outside of the site of usage, as specified in the NRC license No. 11-27304-01, shall comply with the applicable DOT regulations in 49 CFR, Parts 107, 171 - 180, and 390 - 397. 49 CFR 177.817(a) requires, in part, that a person not transport a hazardous material by highway unless it is accompanied by a shipping paper prepared in accordance with 49 CFR Part 172, Subpart C.			
Contrary to the above, from April 15, 2009 to November 2010, the licensee failed to have shipping papers, that were prepared in accordance with 49 CFR Part 172, Subpart C, accompany the licensed material that was transported from the licensee's authorized storage location to temporary jobsites. Specifically, during the NRC inspection at the authorized storage location the inspector observed that the licensee's shipping papers that accompanied portable gauges that were used at temporary jobsites did not contain the following regulatory required information (UN number, reportable quantity (RQ) designation, class 7 designation, correct transport index number, shipper's name and address, radionuclide activity, and emergency contact information).			
This is a Severity Level IV violation (Supplement V).			
Licensee's Statement of Corrective Actions for Item 4, above.			
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.			
Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Gary R. Burkett		12/13/10
NRC INSPECTOR	Roberto J. Torres		12/09/2010

RECEIVED
 DEC 13 2010
 2010

EHM ENGINEERS, INC.

621 North College Rd., Suite 100

Twin Falls, Idaho 83301

Phone: 208-734-4888 Fax: 208-734-6049

TO: US NRL

Attn: Roberto J. Torres

FAX: 817-860-8263

FROM: Brian Lupar RSO

DATE: 12/13/10

RE: Signed NRL 591 M Form

RECEIVED

DEC 13 2010

2:55 PM

Comments:

_____ Pages Sent (Including Cover Sheet)

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: EHM Engineers, Inc. 621 North College Road, Suite 100 Twin Falls, Idaho 83301 REPORT NO: 2010-001	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125	
3. DOCKET NUMBER 030-32261	4. LICENSE NUMBER 11-27304-01	5. DATE OF INSPECTION December 7, 2010

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.


Title 10 CFR 71.5(a) requires, in part, that each licensee who transports licensed material outside of the site of usage, as specified in the NRC license No. 11-27304-01, shall comply with the applicable DOT regulations in 49 CFR, Parts 107, 171 - 180, and 390 - 397. 49 CFR 177.817(a) requires, in part, that a person not transport a hazardous material by highway unless it is accompanied by a shipping paper prepared in accordance with 49 CFR Part 172, Subpart C.

Contrary to the above, from April 15, 2009 to November 2010, the licensee failed to have shipping papers, that were prepared in accordance with 49 CFR Part 172, Subpart C, accompany the licensed material that was transported from the licensee's authorized storage location to temporary jobsites. Specifically, during the NRC inspection at the authorized storage location the inspector observed that the licensee's shipping papers that accompanied portable gauges that were used at temporary jobsites did not contain the following regulatory required information (UN number, reportable quantity (RQ) designation, class 7 designation, correct transport index number, shipper's name and address, radionuclide activity, and emergency contact information).

This is a Severity Level IV violation (Supplement V).

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Roberto J. Torres		12/09/2010