





Bellefonte Nuclear Plant, Units 3 & 4
 COL Application
 Part 2, FSAR



Formation of Fe-Depleted "Bleached" Zones
 Source: Reference 480