



89 Summer Street, Marshfield, MA 02050 781-834-5279 fax 781-834-5281

December 07, 2010

Nuclear Regulatory Commission
11555 Rockville Pike
Rockville, MD 20852

Subject: Error Notification

Dear Sir/Madam:

Per Part 21, "Reporting of Defects and Noncompliance", and per our in-house Quality Assurance Procedures, enclosed please find Phi-Delta, Inc. (PD STRUDL) BER Report No. B6.0-244.

PD STRUDL is a software program that is used by many Architectural and Engineering (A&E) firms and electrical utilities for the Analysis and/or Design of structural components in a nuclear power plant.

We have already notified all our known users of the error.

Please note that the signed Certified Mail Receipt will be used as the acknowledgement that you have received this notice.

Should you have any questions or need more clarification, please do not hesitate to contact this office, Via Phone (781) 834-5279, or via Fax (781) 834-5281 or via E-Mail at PHIDELTA10@AOL.com.

Thank you.

Sincerely,

Som P. Vish / For VPF

Victor P. Ferrarini, PE
QA Manager
Phi-Delta, Inc.

encl.

PHI-DELTA BUG/ENHANCEMENT/ERROR REPORT
(BER)

BER REPORT NO. B6.0-244

APPLICABLE PROGRAM PRODUCT:

PD STRUDL _____ E/PD STRUDL _____ OTHER _____ ALL: X

REPORTER: PD,SPV _____ DATE: 12/05/2010

RECORDER: PD, SPV _____ DATE: 12/05/2010

PLATFORMS AFFECTED: ALL: X IBM: ___ VAX: ___ PC: ___

OTHER (IBM RISC, SGI): _____

VERSION(S) AFFECTED: 1992 Onwards

(if an enhancement, complete at time of release)

DESCRIPTION:

For Ping Code (ASME and B31.1), when one or more equations are checked for more than one load, the code checking results are correct. But the following may be incorrect:

1. The Book Format Summary Report for Pipe Check Summary may have wrong results,
2. If the Piping code check results are used for the checking of Welded Pipe Attachments (WPA), the existing stresses and hence the interaction ratios may be wrong.

The error will be corrected in the next version.

IF A BUG,

LEVEL # 4

SIGNATURE

Som P. Visk

DATE: 12/06/2010

CONDITIONS UNDER WHICH IT OCCURS:

None

CIRCUMVENTIONS, IF ANY:

None

**CUSTOMER LOG TO WHOM PD STRUDL ERROR
REPORT B6.0-244 WAS DISTRIBUTED**

Mr. Asit Parekh
American Electric Power
500 Circle Drive
Buchanan, MI 49107

Mr. Steven Greer Or QA Manager
Altran Corporation
451 D Street
Boston, MA 02210

Dr. Tsiming Tseng
Stevenson & Associates
275 Mishawum Road
Suite 200
Woburn, MA 01801

Mr. Thomas G. Mudge
URS - Washington Group International
510 Carnegie Center
Carnegie Center Drive
P. O. Box 5287
Princeton, NJ 08543-5287

Entergy Nuclear Northeast
Manager of Operating Experiences
440 Hamilton Ave
White Plains, NY, 10601

Entergy Nuclear Northeast
Director of Nuclear Safety Assurance
440 Hamilton Ave
White Plains, NY, 10601

Indian Point Energy Center (Indian Point 2 & 3)
Manager of Operating Experiences
P.O. Box 308
295 Broadway, Suite 1
Buchanan, NY, 10511

Indian Point Energy Center (Indian Point 2 & 3)
Director of Nuclear Safety Assurance
P.O. Box 308
295 Broadway, Suite 1
Buchanan, NY,

James A. Fitzpatric Nuclear Plant
Director of Nuclear Safety Assurance
P.O.Box 110
268 Lake Road East
Lycoming, NY, 13093

Entergy Nuclear Northeast
Manager of Operating Experiences
440 Hamilton Ave
White Plains, NY, 10601

Pilgrim Nuclear Power Station
Manager of Operating Experiences
600 Rocky Hill Road
Plymouth, MA, 02360

Pilgrim Nuclear Power Station
Director of Nuclear Safety Assurance
600 Rocky Hill Road
Plymouth, MA, 02360

Nuclear Regulatory Commission
11555 Rockville Pike
Rockville, MD 20852

Please note that the Error Report was sent only to those customers who has licensed PD STRUDL Pipe Stress Module.